

WATER MANAGEMENT CASE STUDY



Company: Aricemex
Location: Cambrillos, Spain
Type of site: Quarry

Potential impact on water or groundwater

The potential impact is the inefficient use of water.

The aggregates, washed in treatment plants, have a high water consumption. In many cases, settlement ponds, which are large areas of clay-laden water arranged in such a way as to promote the settlement of solids enhancing the evaporation, are used. These ponds have high cleaning and maintenance costs.

Action on

Treatment plant for recovering sludge

Description of the good practice

The Company introduced a closed circuit to the aggregate washing process so that the used wash water was piped to a sludge settling tank to extract the suspended solid particles which can then be used in restoration areas. The clean water from the settling tank is then returned to the washing circuit.

Description of the positive effects on water/groundwater

- Reduced consumption of water
- Elimination of sludge in settlement ponds
- Obtaining of inert products so that they can be used in restoration and landfilling.

